

## **CNC Production Operator**

Minimum 6 months experience in CNC machining.  
Experience in Fanuc controls a plus.

### **Duties and Responsibilities Include the Following:**

- Possess a working knowledge of CNC milling and turning.
- Use standard gauging for product conformance verification; have basic understanding of SPC.
- Read blue prints and apply its meaning as pertained to product.
- Skilled at changing and adjusting tooling as necessary.
- Understand and maintain production requirements.
- Possess a working knowledge of machine tooling.
- Follow and signoff on employee responsibility sheets.
- Follow all safety rules and guidelines while working in a professional manner.
- Required to maintain a clean and organized work area.
- Required to use and follow the Quality System of Swihart Industries.
- Other duties as assigned.

### **Skills and Experience:**

- \* 3rd shift opportunities w/shift premium.
- \* Minimum 6 mos. experience in CNC machining.
- \* Requires capability to lift 30-50 lbs. repetitively.
- \* Flexibility to work required overtime.
- \* Experience in Fanuc controls a plus.

### **Physical Demands/Work Environment:**

The physical demands described here are representative of those that must be met by an employee to successfully perform the essential functions of this job. Reasonable accommodations may be made to enable individuals with disabilities to perform the essential functions.

While performing the duties of the job, the employee is regularly required to talk or hear. The employee is frequently required to stand and occasionally required to sit, walk, and use hands to finger, handle or feel. Job responsibilities demand exposure to production. Company lifting limitations will be enforced. Specific vision abilities required by this job include close vision and ability to adjust focus.